

| n° | edificio | P.H. | R. | M.N. | A. |
|----------------|----------|------------|------------|-----------|-----------|
| 1 | 4.340 | 20 | 22 | 0 | 0 |
| 2 | 6.738 | 0 | 0 | 4 | 4 |
| 3 | 7.5657 | 32 | 50 | 27 | 14 |
| 4 | 8.5657 | 0 | 0 | 0 | 0 |
| 5 | 9.978 | 0 | 0 | 6 | 0 |
| 6 | 12.862 | 10 | 10 | 0 | 9 |
| 7 | 13.715 | 5 | 6 | 0 | 0 |
| 8 | 13.4849 | 2 | 3 | 2 | 3 |
| 9 | 14.720 | 0 | 0 | 2 | 1 |
| 10 | 14.824 | 43 | 44 | 0 | 0 |
| 11 | 44.157 | 0 | 1 | 1 | 0 |
| 12 | 47.859 | 4 | 4 | 0 | 1 |
| 13 | 47.949 | 6 | 6 | 3 | 3 |
| 14 | 48.814 | 0 | 0 | 1 | 0 |
| 15 | 48.985 | 0 | 0 | 8 | 0 |
| 16 | 50.889 | 11 | 14 | 28 | 0 |
| 17 | 50.1116 | 1 | 29 | 3 | 2 |
| 18 | 51.371 | 2 | 2 | 2 | 1 |
| 19 | 53.455 | 1 | 1 | 1 | 0 |
| 20 | 54.590 | 16 | 36 | 1 | 0 |
| 21 | 54.792 | 2 | 2 | 0 | 0 |
| 22 | 55.726 | 11 | 11 | 0 | 0 |
| 23 | 55.884 | 5 | 6 | 0 | 2 |
| 24 | 56.591 | 5 | 5 | 0 | 0 |
| 25 | 56.596 | 2 | 2 | 0 | 0 |
| 26 | 56.1033 | 0 | 4 | 0 | 0 |
| 27 | 63.855 | 1 | 1 | 2 | 0 |
| 28 | 70.324 | 2 | 7 | 1 | 0 |
| 29 | 74.2049 | 0 | 0 | 2 | 1 |
| 30 | CC.1667 | 2 | 6 | 0 | 3 |
| 31 | CL.3033 | 0 | 0 | 1 | 1 |
| TOTALES | | 183 | 272 | 95 | 45 |

Referencias:

P.H.: Prueba hidráulica.

R.: Recarga de matafuego.

M.N.: Provisión matafuego nuevo.

A.: Amurado de matafuego con
su correspondiente baliza.



Arq. DUMM Carlos Jorge